

MEMORANDUM

TOM M. ☒
PHIL ☐

TO: File

FROM:

DATE: August 21, 1997

SUBJECT: Torrance - DPS cooperation

COPIES TO: Overturf, Stavale, file.

WE NEED TO GET THIS
TO A HIGH ENOUGH LEVEL
TO GET THE MESSAGE DOWN TO
THE C-6 FOLKS.... ITS GETTING
VERY BAD. HOPEFULLY BEFORE
BISSET LEAVES HELL GIVE US
SOME "ONE COMPANY" SUPPORT @
C-6 SINCE THEY WORK FOR HIM -
AT LEAST THE WORST UNION GUYS!!
HOPEFULLY WE CAN ENLIST THE
NEW D.P.'S. MGT. TEAM AND
STEVE'S REPLACEMENT.

Below is a brief summary of events that is causing a real problem in our coordination efforts with DPS personnel on site:

THO

1. Compressed Air System

- Our engineer was not allowed to enter facility and was rudely treated and belittled by Facilities. Engineer did not want to return to facilities until I straightened things out.
- Department representatives changing and making outrageous requests. No significant assistance was provided by Facilities in coordinating the drawings.
- Dust collector maintenance problem had to go all the way to Steve Bisset for resolution because Facilities would not provide us with any help what so ever.
- A last minute change to provide the Maintenance Dept. with a new compressor met with resistance when we were not allowed the use of a fork lift to off load the compressor. This got real ugly. I suggest we get DPS to transfer a fork lift to us for our sole use.

2. Phase 2 Demolition

- No cooperation in receiving DPS estimate and scope of work for relocating Bldg. 14 and 15 (\$250,00.). We were told to make our own estimate.
- No cooperation in getting drawings (space rqmts.) from Facilities. Scheduled meetings go by with no DPS attendance.

Commentary - Never in all my 37 years of service with the company have I run across such a group of people so uncooperative, rude, bad attitude and negative. I've been very successful in working with all the components of the company except this one at Torrance. I'm sure they have there reasons but why we can't work them out is mystery to me.